


## Parts List

[x]	Part #	Sub-Assembly	Description	Copies	# Cut	Thick	Width	Length	Material Type	Material Name	Bandin g	<Info >	Diagram #s
[ ]	A	Corn Hole	Top	2	0	1/2"	24"	48"	Sheet Good	Baltic Birch	None		B1
[ ]	B	Corn Hole	Sides	4	0	1/2"	3 1/2"	47 1/2"	Sheet Good	Baltic Birch	None		B1
[ ]	C	Corn Hole	Short Notch	2	0	1/2"	3 1/2"	23"	Sheet Good	Baltic Birch	None		B1
[ ]	D	Corn Hole	Short Full	2	0	1/2"	3 1/2"	24"	Sheet Good	Baltic Birch	None		B1
[ ]	E	Washers	Bottom	2	0	1/4"	14"	14"	Sheet Good	Baltic Birch	None		A1
[ ]	F	Washers	Sides	8	0	1/4"	3 1/2"	14 1/2"	Sheet Good	Baltic Birch	None		A1




**[A1] Baltic Birch: 1/4" x 60" x 60"**

Vendor: Liberty Hardwoods Bin:

[ ] 1 of 1 this size Qty this diag.: 1 Grain: None Stock Trim: 0"::0" Standard Layout

Kerf: 1/8" Part Padding: 0" Waste: 77.8% Final Cut Dimensions

Part #	Sub-Assembly	Description	Copies in Layout	Thick	Final Cut Y	Final Cut X	Rough Y	Rough X	Banding	<Info>
E	Washers	Bottom	2	1/4"	14"	<b>14"</b>	14"	<b>14"</b>	None	
F	Washers	Sides	8	1/4"	3 1/2"	<b>14 1/2"</b>	3 1/2"	<b>14 1/2"</b>	None	



**[B1] Baltic Birch: 1/2" x 60" x 60"**

Vendor: Liberty Hardwoods Bin:

[ ] 1 of 1 this size	Qty this diag.: 1	Grain: None	Stock Trim: 0"::0"	Standard Layout
Kerf: 1/8"	Part Padding: 0"	Waste: 8.4%	Final Cut Dimensions	

Part #	Sub-Assembly	Description	Copies in Layout	Thick	Final Cut Y	Final Cut X	Rough Y	Rough X	Banding	<Info>
A	Corn Hole	Top	2	1/2"	24"	<b>48"</b>	24"	<b>48"</b>	None	
B	Corn Hole	Sides	3	1/2"	3 1/2"	<b>47 1/2"</b>	3 1/2"	<b>47 1/2"</b>	None	
B[R]	Corn Hole	Sides	1	1/2"	<b>47 1/2"</b>	3 1/2"	<b>47 1/2"</b>	3 1/2"	None	
C[R]	Corn Hole	Short Notch	2	1/2"	<b>23"</b>	3 1/2"	<b>23"</b>	3 1/2"	None	
D[R]	Corn Hole	Short Full	2	1/2"	<b>24"</b>	3 1/2"	<b>24"</b>	3 1/2"	None	